Sanitized Copy Approved for Release 2010/05/25 : CIA-RDP89B00569R000200150074-6 0550Z 24 JAN 63 SECRET DIRECTUR OSA/TCO (1-2-3-4-5-6-7-8) PRIORITY TOR 09352 24 Jan 63 IN 63517 PRITY 2909 1. THIS IS TECH EVAL MISSION 3215.

25X1

25X1

- P BAND HOISY FROM AC ON. L BAND AND X BAND QUIET. S BAND MOISY. NOISE REGULAR, PROBABLY MOTOR ABOARD PLANE. REQUEST IN PUTURE IF TAPE IS CUT OFF BEFORE AC OFF, COMMENTS BE INCLUDED IN DATA SHEETS. THIS MISSION AC ON 0121, AC OFF 0822. ASSUMING CORRECT TIME ON, ONE TAPE RAN OUT 0802, OTHER AT 0755.
- REQUEST WIRENG BE CHECKED. WHEN STRONG SIG UP ON S BAND LEFT, AFTER RECEIVER SWITCHED TO RIGHT SAME SIG UP ON K BAND BUT NOT S BAND. WHEN PLANE CLOSE TO SOURCE SIG UP ON S BAND BOTH SIDES BUT CNLY ON X BAND LEFT. WHEN SIG CHANGED AFTER TURN, S BAND INDICATED TURN BUT X BAND ON LEFT ONLY.

END OF MESSAGE

25 YEAR RE-REVIEW

F-1-L-E 1Cy only

SECRET

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED